MATERIAL SAFETY DATA SHEET

IDENTITY: #8637 VERY BERRY

SECTION I

Manufacturer Name:	Emergency Telephone Number
Shivashade	516-377-7770
28 Rider Pl.	Telephone For Information
Freeport, N.Y. 11520	516-377-7770
	Date Prepared
	April 2007
	Prepared By: Staff

SECTION II - HAZARDOUS INGREDIENTS / IDENTITY INFORMATION

Hazardous Components	OSHA PEL	ACGIH TLV	OTHER LIMITS	PERCENT OPTIONAL
NONE				

SECTION III - PHYSICAL / CHEMICAL CHARACTERISTICS

Boiling Point:........... 212 deg. F   Specific Gravity.(H2O=1)   1.0
Vapor Pressure(mm Hg).... NA   Melting Point..........:   NA
Vapor Density (air=1).... NA   Evaporation Rate.......:   1
Solubility in water...... Complete   (Water =1)
Appearance and Odor: light to amber liquid, berry odor

SECTION IV - FIRE AND EXPLOSION HAZARD

Flash Point (Method Used): None   Flammable Limits: LEL: UEL:
Extinguishing Media: NA

Special Fire Fighting Procedures: NA

Unusual Fire and Explosion Hazards: NA

Stability   Unstable   [ ] Stable [**X**] Conditions to Avoid: None
Incompatibility (materials to avoid): Do not mix with unknown chemicals
Hazardous Decomposition or Byproducts: None
Hazardous Polymerization   May occur   [ ] Will not occur [**X**] Conditions to Avoid: None

 SECTION VI - Health Hazard Data

Route(s) of entry   Inhalation? NO   Skin?   NO   Ingestion? NO
Health Hazards(Acute and Chronic):   Although this product does not contain hazardous
ingredients, contact may irritate eyes and skin and should never be ingested.

Carcinogenicity: NTP? NO   (ARC Monographs)?   NO   OSHA Regulated? NO

Medical Conditions Generally Aggravated by Exposure: NONE

Emergency and First Aid Procedures: Eyes and skin - flush with water. If irritation persists,
see physician. Ingestion - call physician.

SECTION VII - Precautions for Safe Handling and Use

Steps to Be Taken in Case Material is Released or Spilled: Flush or mop up.
Waste Disposal Method: According to federal, state and local authorities
Precautions For Storing and Handling: Keep from freezing.
Other Precautions: None

 SECTION VIII - Control Measures

Respiratory Protection (Specify Type): None
Ventilation   Local Exhaust: Special:
                  Mechanical   :   Other:
Protective Gloves: NA
Eye Protection: Goggles to prevent splashing
Other Protective Clothing or Equipment: None

Work Hygienic Practices: Wash thoroughly after handling.